


			℃		

℃,

。

℃

FIG.1 DERATING CURVE





		_____ _____ °C °C °C °C

°C °C



°C

°C °C



m/m

1/6W 1/8W 1/4WS	T52	3.2±0.3	1.8±0.3	28±2.0	0.40±0.05	2.5Kg-30S
1/4W / 1/2WS	T52	6.0±0.5	2.3±0.3	27±2.0	0.43±0.05	2.5Kg-30S
1/2W / 1WS	T52	9.0±1.0	3.5±0.5	26±2.0	0.56±0.05	2.5Kg-30S
1W / 2WS	T52	11.0±1.0	4.5±0.5	25±2.0	0.65±0.05	3Kg-30S
	T63	11.0±1.0	4.5±0.5	31±2.0	0.65±0.05	3Kg-30S
	T73	11.0±1.0	4.5±0.5	34±2.0	0.65±0.05	3Kg-30S
2W / 3WS	T63	15.0±1.0	5.0±0.5	29±2.0	0.70±0.05	5Kg-30S
	T73	15.0±1.0	5.0±0.5	33±2.0	0.70±0.05	5Kg-30S
3W / 5WS	T63	17.0±1.0	6.0±0.5	27±2.0	0.70±0.05	5Kg-30S
	T73	17.0±1.0	6.0±0.5	32±2.0	0.70±0.05	5Kg-30S
5W		24.0±1.0	8.0±1.0	28±2.0	0.75±0.05	5Kg-30S



m/m



